

## **Minutes**

Special Meeting and Site Inspections April 10, 2019

The Special Meeting and Site Inspections of the Oxford Safety & Health Committee (OSHC) was called to order at 10:12 AM.

The following members were present: Chairman Kelly Weymer, Gordon Gramolini, Sharon Trede, Vice-Chairman Margaret West-Mainor and Jessica Pennell.

## **Approval of Minutes**

<u>MOTION</u> was made by Vice-Chairman Margaret West-Mainor to approve the 12/12/18 Regular Meeting minutes as presented. This was seconded by Jessica Pennell. All were in favor.

### Site Inspections

Police Department

The committee conducted an inspection of the Police Station. (Attachment A)

Senior Center

The committee conducted an inspection of the Senior Center. (Attachment B)

### **Other Business**

Emergency Situation and Evacuation Procedures

Chairman Weymer explained that the evacuation routes are all set to be hung around Town Hall. The Custodian is aware of this and will be putting them up when he can.

Other Matters as Deemed Necessary

Chairman Weymer stated that letters with the committee's recommendations were sent to the Administration and Parks & Recreation back in January. Parks & Recreation has begun to resolve some of our cited items and recommendations.

## Adjournment

MOTION was made by Jessica Pennell to adjourn the meeting at 11:32 AM. This was seconded by Vice-Chairman West-Mainor. All were in favor.

Respectfully submitted by,

Kelly M. Weymer

Chairman

# Attachment A

## Town of Oxford Safety Inspection Checklist

Date of Inspection: 4/10/19

Administrative Data	
Name of Facility Police Department	ent Talanhana
Address 429 Oxford Road Building Representative's Name	Telephone
Inspected By DSHC	
Exit Doors and Emergency Lighting	
Exit Signs Present and Lighted? Yes  Doors Free of Obstructions? Yes  Lighting Fixtures Illuminate Properly When Test Lighten	NO - Front door has no Exit sign - needs one NO - Remove shovels, etc. from back door area This Activated?  Yes  NO - Front hallway exit light doc not work with
Action Taken See "Additional Comments	ii testea
When and By Whom	
Stairwells	
The date History	No 1
	$N_0$ $N/A$
Recommended Action	, ,
Action Taken When and By Whom	
When the Dy Whom	
Housekeeping	
Storage Properly Arranged?  Rubbish Picked Up and Stored Properly?-  Adequate General Maintenance?  Recommended Action Need + b remove fires,  Action Taken  When and By Whom	No No No mep bin + recyclables in back door area
Flammable or Combustible Liquids	
Type and Amount Proper Storage? Recommended Action Cabinet blocked by Action Taken When and By Whom	No Fires - map bin. See above.

# Attachment A

<u>Electrical System</u>			
Circuit Protection and Wiring Adequate?	Yes	No	· :
Use of Extension Cords?	(Yes)	No	
Meter and Panel Boards labeled and Clear?	Yes	No	
Recommended Action			
Action Taken Extension Cord use	acceptable	Le	
When and By Whom			
Fire Detection and Alarm System			
Fire Detection and Alarm System			
Monitoring Company			
Address		Telephone	
System Tested within 12 Months?	Yes	No .	
Recommended Action			
Action Taken			
When and By Whom			
Fire Extinguishers			
Appropriate Type for Hazards?	Yes	No	
Extinguishers Services Within 12 Months?	Vai	No	
Recommended Action	163	INU	
Action Taken	· · · · · · · · · · · · · · · · · · ·	<del> </del>	
Action Taken When and By Whom	· · · · · · · · · · · · · · · · · · ·		
When and By Whom		<del>:</del>	
	•		
Additional Comments:			
	1,		- 1 //
1. Doors that are not exits need. 2. Exit sign in hundr norm - need	<u>Signs Stati</u>	ng "Not An Es	cit
n Cu and a land			`
2. Exit sign in lunch room - need	6-to cover	arnows.	
3. Need another Exit sign in be	tween back	door aver +	lykor nom en
also in office area going on	t into hal	levay	
		U .	

## **Attachment B**

# Town of Oxford Safety Inspection Checklist

Date of Inspection: 4/10/19

Administrative Data	
Name of Facility  Address 10 Old Church Road  Building Representative's Name Inspected By 05 HC	
Exit Doors and Emergency Lighting	
Exit Signs Present and Lighted?  Doors Free of Obstructions?  Lighting Fixtures Illuminate Properly When Test Lights Activated?  Yes  Recommended Action  Action Taken  When and By Whom	No
<u>Stairwells</u>	
Adequate Illumination? Yes No Handrails Present and Secure? Yes No Recommended Action Action Taken When and By Whom	
Housekeeping Storage Properly Arranged? Yes	
Storage Properly Arranged?  Rubbish Picked Up and Stored Properly?  Adequate General Maintenance?  Recommended Action forwer fires in mechanical room away from Exit a  Action Taken  Remove debris, shingles, gund, etc. from walk  When and By Whom	ber And way
Flammable or Combustible Liquids	
Type and Amount Proper Storage?  Recommended Action Action Taken When and By Whom	

# **Attachment B**

<u>Electrical System</u>		
Circuit Protection and Wiring Adequate?	Yes	No ·
Use of Extension Cords?	Yes	No
Meter and Panel Boards labeled and Clear?	Yes	No
Recommended Action		
Action Taken <u>Extension and use ac</u>	centable	
When and By Whom	7	
Fire Detection and Alarm System		
Manitorina Communication		
Monitoring Company		T. 1. 1
Address System Tooted Within 12 Manth 2	77	Telephone
System rested within 12 Months?	Y es	No
Recommended Action		
Action Taken When and By Whom		
When and By Whom		
Fire Extinguishers		<del>-</del>
		·
Appropriate Type for Hazards?	Yes	No
Extinguishers Services Within 12 Months?	Yes	No ·
Recommended Action		
Action Taken		
When and By Whom		
1122 10		
Additional Comments:		
1 Craft Para - Should have for	autor anis	clar more of deep to
1. CAUTT ROUTH STOKER PAUL TITE	exTIPSUS	They present duce 10
1. Craft Room-Should have fire. Combustables	J	
2. All doors that are not an exi	+ should	d have signs stating
4011 1 5014		
"Not An Exit"	······································	
3. Billiard Room Cabinet is blocks	ne emero	renew lights
	0 0	
4. Back patro Ceiling is falli	uga Cru	inbling at the seam
4. Back patro ceileig is falli. 5. Office over store room has a	2 leak/	hole in ceiloria.
	<del></del>	7